

Registration No. 11339

Case No. _____

HA 580-038889

5-28-99

COMPLIANCE STATUS REPORTDate of Report 5-24, 19 99 at 8:00 a.m.

Source Name <u>Ash Grove Cement Co.</u>	Responsible Person, Title <u>Henrik Voldbaek, Mgr</u>
Location <u>3801 E. Marginal Wy S.</u> <u>Seattle, WA 98134</u>	

☐ No violations of PSAPCA's regulations were observed at the time of my inspection, with respect to the areas of the facility I inspected.

☒ During my inspection I noted the following deficiencies:

Emissions of uncontrolled fugitive dust
during handling of ball mill balls.
No control measures implemented.
Report how emissions will be controlled
during future activities such as this
to ensure compliance with Reg I 9.15(a).
Please note that this was a violation
of Reg I 9.15(a) & failure to respond
may result in further enforcement
actions.

Please submit a written report within ten (10) working days describing the necessary corrective action you have taken or propose to take, including a schedule, to address the above deficiencies.

Issued by: M. M. [Signature]

Received by _____

Signing this is not an admission of guilt

ASH GROVE CEMENT COMPANY



"WESTERN REGION"

June 14, 1999

Elizabeth Gilpin
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report Dated 05/24/99

The following is further information as you requested on abatement of fugitive dust during the handling of mill balls.

In the past it appears that uncontrolled fugitive dust was created when a Front End Loader was used to dump the finish mill balls into the hopper of our sorter. To ensure compliance with Reg. 19.15(a), a water misting system will be used during this operation. This would most likely be in the form of several nozzles mounted near the top of the hopper to cover the open area of the hopper with a water mist.

Sincerely,

J. Trygve Grey
Process Engineer

AGCS2M000725